



Installation Manual











Pre-installation



TOOLS REQUIRED



HARDWARE INCLUDED


A  (x3)  Ø10(x3)  M8x110 (x3)		 (x1)		B  (x1)		C  (x1)  (x1)  M5x26 (x1)	
D  (x1)  M4X2		E  (2)		F  (x1)			
G  (3)  M6X25 (12)		H  (x1)  (X1)  Ø8(x4)  ST4. 2X32 (x4)		 (x3)			
J 5x6 (x4)  2mm 2.5mm 4mm							

Installation




Installation

2




3

- A**
- (x1)
- Ø10 (x3)
- M8x110 (x3)
- (x3)
- I**
- (x3)



4


G




(x3)



M6x25
(x 12)




1





x3




2



5




6



7

C




(x1)

B




(x1)



8

H



(x1)



(x1)




ST4. 2X32
(x4)



Ø8 (x4)




≥30mm




1


(x1)



2



3




4

www.gosimat.pt | www.openspace.pt

9

C







(x1)

J



2mm
(x1)



10



(x1)








J



2mm
(x1)



4mm
(x1)



11

C



M5x26
(x1)



(x1)

J



2.5mm
(x1)

D



(x1)



M5x6 (x2)

